

## **MODEL CODE BREAKDOWN**







PARTS ARE THE SAME FOR RIGHT AND LEFT HAND ROTATION. WHEN ORDERING SPARE CARTRIDGE PARTS, IT IS RECOMMENDED THEY BE OBTAINED IN CARTRIDGE KITS. KITS ARE ASSEMBLED AND TESTED BY VICKERS FOR EITHER RIGHT OR LEFT HAND ROTATION. IF LEFT HAND ROTATION IS REQUIRED, IT SHOULD BE SPECIFIED ON PARTS ORDER BY ADDING SUFFIX "L" TO CARTRIDGE KIT NUMBER: FOR EXAMPLE 581663-L.

For satisfactory service life of these components, use full flow filtration to provide fluid which meets ISO cleanliness code 18/15 or cleaner. Selections from Vickers OFP, OFR, and OFRS series are recommended.

Litho in U.S.A.




## Service Parts Information

Thru Drive Vane Type

Pumps

45VT\*\*\*\*-2\*\*\*20-28\*




Vickers, Incorporated

1401 Crooks Road Troy, Michigan 48084 Revised 10-1-85

I-3151-S



Seals must be completely wetted at assembly with an SAE 10W motor oil of "SE" quality or an industrial hydraulic oil equivalent.



|  | MODEL   | ADAPTER | SCREW     | WASHER    | ■ADAPTER |  |
|--|---|---------|-----------|-----------|----------|--|
|  |   |         | (4 REQ'D) | (4 REQ'D) | KIT      |  |
|  | 45VTA   | 584936  | 298147    |           | 941296   |  |
|  | 45VTB   | 584922  | 290141    |           | 941297   |  |
|  | 45VTC   | 581833  | 298148    | 582 51 9  | 941298   |  |
|  | THE TABULATED ADAPTER KITS HAVE F3 SEALS STANDARD KITS ARE NOT PROVIDED FOR SERVICE |         |           |           |          |  |
|  |   |         |           |           |          |  |

•ALSO INCLUDED IN CARTRIDGE KIT

| MODEL | ▲ STD    | F3       |  |
|-------|----------|----------|--|
| MODEL | SEAL KIT | SEAL KIT |  |
| 45VTA | 920201   | 920202   |  |
| 45VTB | 920203   | 920204   |  |
| 45VTC | 920205   | 920206   |  |

| MODEL     | RING   | *VEI   | COUPLING |
|-----------|--------|--------|----------|
|           | MING   |        | KIT      |
| 45VTA286  | 223172 |        | 941305   |
| 45VTB286  | 83003  | 239751 | 941306   |
| 45VT C286 | 103989 |        | 941307   |

SHAFT AND COUPLING MUST BE SERVICED AS A KIT

