

Service Parts Information

VICKERS.


HIGH TORQUE LOW SPEED VANE MOTORS MHT 380/440/500





PREVENTS MISALIGNMENT OF SPRINGS AND GUIDES.

MODEL CODE BREAKDOWN



For satisfactory service life of these components, use full flow filtration to provide fluid which meets ISO cleanliness code 18/15 or cleaner. Selections from Vickers OFP, OFR, and OFRS series are recommended.